

## City of Milpitas

## **Engineering Division**

455 E. Calaveras Boulevard, Milpitas CA 95035

To:	Potential Bidders
Project Name/No.	Storm Pump Station Improvements "Re-roof", Project No. 8188 & 8162
From:	Fariborz Heydari, Project Manager
Date:	September 17, 2010
Subject:	Checklist for Common Bidding Errors
checklist is for your "Instruction to Bidd	ist of areas to avoid common bidding errors on City projects. This r convenience only, you are reminded to read and follow Section B - lers", in the contract documents:  complete information on bid forms and be sure forms are completely
	contractor's license number on required form;
	bid bond (total base bid);
	unit costs are written out on bid schedule;
	eledge addenda and include it with bid (One addendum has been issued 9/17/10);
☐ Sign bid	forms;
☐ Assign o	compensations in accordance with bid proposals-don't unbalance bids;

☐ List subcontractors & percentage of total contract completely.